






















IF-MY-M3002 Side table





PART NO.	PART PHOTOGRAPH	PART NAME	QUANTITY
1			1
2			1
3			1
4			1
5			1
6			1
7			1
8			1
9			1
10			1
11			2
12			2
13			2
14			2
15			4
16			2
17			


HARDWARE NO.	PHOTOGRAPH OF PART	DESCRIPTION/SIZE	NO OF PCS
101		L=40	6
102		Φ 15	16
103		Φ 6X30	12
104		Φ 10	4
105		Φ 5X50	4
106		Φ 4X12	20
107		Φ 4X30	11
108			2
109		L=40	10
110		M4X25	2
111		L=28	12
112		Φ 12	12
113			1
114	 114A 114B	L=300	2




113X1	107X8
	
	Φ 4X30


1





113X1	102X8	109X8
		
	$\Phi 15$	L=40




113X1	106X8	114X2	
	 $\Phi 4 \times 12$	 L=300	  114B





113X1	101X2	102X4	109X2	111X4	112X4
					
	L=40	Φ 15	L=40	L=28	Φ 12





113X1	107X3
	
	Φ4X30


5





113X1	101X4	102X4
		
	L=40	$\Phi 15$





113X1	103X8	104X4	105X4
			
	Φ 6X30	Φ 10	Φ 5X50




113X1	103X4	108X2	110X2	111X8	112X8
					
	Φ 6X30		M4X25	L=28	Φ 12



X2

113X1	106X12	114X2	
	 Φ 4X12	 L=300	 114A  114B



X2

