





16



17



Assembly Instruction



Fittings




A=20

B=20


C=20

D=44

E=12



F=1



J-1=2

J-2=2

J-3=1



G=12



H=1



I3=2



N=3



L=8



U=4



P=24



V1=24




Z1=6




Z2=6


1




2




3




4




5




6




7





8




9




10




11




12




13




14



14-2



14-3



X3

15

