




Assembly Instructions




A*1PC




B*1PC




C*1PC




D*1PC




E*1PC



F*1PC



G*4PCS



H*10PCS




I*40PCS




J*4PCS


STEP 1




STEP 2




STEP 3




STEP 4



STEP 5



STEP 6



STEP 7

